



# 18: SIDE SEWER INSPECTION REPORT

## Information

Sewer Lateral Line: Connection to City Sewer Line Observed (Photo)	Sewer Lateral Line: Distance to City Sewer Line Connection (in feet)	Sewer Lateral Line: Lateral Line Access (Cleanout) Location (Photo)
Yes	80	Basement Cleanout
		

### Sewer Lateral Line: Lateral Line Generally Acceptable

The sewer lateral line was found to be in generally acceptable condition at the time of inspection. Any deficiencies will be noted below.

### Sewer Lateral Line: Link to Video

The video of the inspection can be found at the following link: <https://youtu.be/UIY42m0h1sg>

### Sewer Lateral Line: Pipe Material (Photo)

SDR 35, Clay, Liner inside pipe

